





A.1. Location of Testing Points (NTS)





### A.2.1. DUTCH CONE PENETROMETER TEST (ASTM D-3441)





### A.2.2. DUTCH CONE PENETROMETER TEST (ASTM D-3441)

